


*Typical Return Loss*



International Manufacturing Services, Inc. 50 Schoolhouse Lane Portsmouth, RI 02871-2418

*RLX-2512 50Ω Terminator  
ANK-2512 50Ω Terminator*